


1955 Packard Clipper engine showing location of ignition wire support bracket on LEFT side of engine. The right side also has two. The senior Packard engines have same arrangement. The two rearmost wires on each side are longer than on 1956 Packards and Clippers which use two larger support brackets.



Later 1955 models use two ignition wire support brackets, one on each valve cover same as the 1956 cars.

1956-type ignition wire support bracket, one per side.

Heinmuller Packard Parts,
Jan. 2019